




SK NÁVOD NA MONTÁŽ
 CZ MONTÁŽNÍ NÁVOD
 HU SZERELÉSI UTASÍTÁS
 DE MONTAGEANLEITUNG


SINGA 12

	1096	mm
	399	
	410	











ID	ID	Part	QTY	Ratio
02911	②	352*390*16	1x	1/1
00957	③	1096*410*16	1x	1/1
05019	④	352*390*16	1x	1/1
03288	⑤	1096*410*16	1x	1/1
03687	⑥	232*1090*2,5	1x	1/1
03599	⑦	352*390*16	1x	1/1
01193	⑧	523*389*16	2x	1/1
01106	⑨	542*218*16	1x	1/1
01197	⑩	542*218*16	1x	1/1



27000,00 Ø8x30	22250,00 Ø4x25	30080,00 	21102,00 Ø1,6x20	70013,01 	70021,01 	36001,00 	36001,00 	36050,00 	70022,02
A 20x	B 5x	C 5x	D 25x	G 20x	H 16x	J 4x	K 4x	L 2x	M 2x
22243,00 Ø3,5x15		22400,00 M4x30	32030,00 						
N 16x	P 12x	Q 4x	R 2x						



H 12x	J 4x	K 4x	N 8x	Q 4x	R 2x



A 20x	G 20x	H 4x

